

Last Night's Fire Alarm



OakBridge Board

Thu 5/9/2019 10:54 AM

To: OakBridge Board

Cc: BishopREM@hotmail.com ↗



Sleepy Good Morning,

Last night's fire alarm was caused by a faulty hallway ceiling fire alarm due to age. These hard-wired ceiling alarms will set off the building alarm if not working properly. Unfortunately, there is no PM or indicator showing such an alarm is ready to fail or in need of replacing.

Our fire alarm vendor was called and replaced the faulty ceiling fire alarm. The building was made fire alarm ready at 3:30AM last night.

We are sorry for the early morning wake-up alarm and thank you for your understanding.

Regards,
Board of Directors
Bishop Real Estate Management 880-6464